

1m,9,37.

See paid

F.E.

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME Steel Non-propelled barge "UNO" Rpt. Rot. No. 27262

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

| | | | |
|---------------|--------------------------------------|-----------------------------|--------------------|
| | Metric | | |
| 1st Long. No. | <u>158</u> | Depth "d" | <u>-</u> |
| 2nd Long. No. | <u>466</u> | Proportions = $\frac{L}{D}$ | <u>10.12</u> |
| Framing | <u>Bulb angle frames as approved</u> | Sheerstrake | <u>As approved</u> |

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100A1 "Barge", "Carrying petroleum in bulk"

Subject to two ~~additional~~ lengths of 7/8" chain cable being supplied.

1 Dk.

DTf 19t, FPT 24t, APT 30t.

FK, 8BH., pt.cem.

F 17'

O.L. 137.9'.

[Signatures]
20.9.38



© 2019

Lloyd's Register
Foundation

W132-0126