

Surveyed Afloat or in Dry Dock?

Name of Dock

Destined Voyage

WB=CellDBorDBa

feet; uE&B

feet; f

feet

total capacity

tons. FPT

tons; APT

tons; MT

feet

tons.

Particulars of Classification (which must be precisely as in Register Book & Supplement)

N.B. All alterations in the existing records should be underlined.

CHARACTER

Machinery & Survey (including date of)

2m.11.35.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

"MIDORI MARU"

Report

Lon.

No. 103494

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

BS due 10.37

The class is subject to the after well in engine room being thoroughly cleaned, port and starboard, cement removed from the bottom, and specially examined at the next annual survey.

The Kobe Surveyors now forward a translation of a letter from the Owners to the effect that it has been decided to withdraw this vessel from the Society's classification.

It is submitted the vessel's class be withdraw from the Register Book and Three Dots (...) inserted in lieu thereof indicating withdrawal of class at Owners' request.

21.2.38

*[Signature]*



© 2021

Lloyd's Register Foundation

W1321-0218

d Vessels  
Yes  
ned  
removed)  
anged)  
mean diamr  
size  
Rigging  
ok consequent up  
to have record