

3m, 8, 21.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME *Stat S.S. "SEMIRAMIS"*Report *Sfo*No. *3627*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey

When due

100-A-1. (Steel) Carrying petroleum in bulk.
 2 Dks (Steel) & Webframes. Longitudinal framing
 Cell DB 0.6 x B 81' 23st, ITF 32' 32st, FPT 9st, APT 103st
 FK, 15 Bx1 (11 to upper Dk, A to 2nd Dk) ft Rep, A. CP.

P110' B33' F57' Muly Off

23-11-21

Spacing
 BEAMS, Second Deck, Single Angle, Bulb
 Angle, Plate, Tee Bulb, or Channel
 Spacing

Deck. Material & thickness

Deck Stringer Plate, breadth & thickness

36

W1324 0072