

F.E.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME *Steel S* M.V. CHOAN MARU Rpt. *Kdt* No. 5665

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/02.)

1st Long
Transverse No. 6543

Depth "d" 20'

Framing: Table No. ✓

Description *Bulk angle frame as approved*

2nd Longitudinal No. 19488

Proportions $\frac{\text{Length}}{\text{Depth}} = 12.37$

~~Deck~~ Sheerstrake *as approved*

Revised Rule

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✱ 100 A.1. (Steel).

2 D⁶ (Stl - Upper ws)

Cell D.B 232' 4646, Side Tanks in ER 735, F.P.T. 245, A.P.T. 145.

F.K, 4 B.H, pt Cen, Lloyds A.C.P.

P 29', B 100', F 37'.



© 2021

23.5.27

Lloyd's Register Foundation

W1327-0046