

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME STEEL S.S. "YAKUMO MARU" Rpt. Yka No. 2502

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 71 Depth "d" 16-6

Framing: Table No. 3 page 10 Description Bulb angle as approved

Longitudinal No. 21655

Proportions Length = 8-7
Depth =

Bridge Deck Sheerstrake as approved

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100 A-1. (steel), as recommended.

2 Dks (steel)

Cell DB 262' 587t. FPT 58t. APT 56t.

FK. 5 BH. Cem. A.&C.P. P. 25', B 92', F 30'.

M
ars
25-8-19



© 2021

Lloyd's Register Foundation

W1330-0102