

50,8,12.

Noise Carrier

F.E.

Received by Chief Ship Surveyor 8. 4. 13

Received from Chief Ship Surveyor

VESSEL'S NAME Miss Frieda

Rpt. Bo

No. 718

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/03.)

Transverse No. 73.0

Depth "d" 15.75

Framing: Table No. 3 page 12

Description Channels as approved


Longitudinal No. 21900

Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{10.7}{1}$

Upper Deck Sheerstrake as approved

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

÷ 100 A. 1 ("Steel") as recommended
÷ 100 A. 1. (SH)
1 D.K. (SH) Considered framed topside tanks
W. B. Cell u E.P. 56' f 190' 820t J.P. 286. A.P. 62t.
Topside tanks 166' 505t. Transverse topside tanks 233t
J.K. 5 D.H. C.m. a.g.l. P P80, B25 F39 MCHY APT

B. M.

9. 4. 13
Lloyd's Register
Foundation
WI334-0042