

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

No 3.

Rpt.

Yha

No. 6115

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/12.)

Type of Engine

Oil Engines 4 S. C. S. A

7 cy. 14 $\frac{3}{8}$ " - 19 $\frac{1}{16}$ "

~~If Boilers fitted with forced draught~~

Tail Shaft. If fitted with a continuous liner

Yes

If fitted with an outside gland of

approved type

no

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed + Rule 9-37

The Rules for the notation


OB. 12/16.

strengthened for sea navigation
have been complied with

Yha

17.8.37

Note. Donkey boiler to be examined annually.




© 2021

Lloyd's Register
Foundation

W1334-0068