

declined?

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

completion of Electric instal

Glasgow 31844  
Barcelona 921

191  
te


Survey now complete.

It is submitted that  
this vessel is eligible for  
THE RECORD.

Elec light

Jff

11.12.12



© 2021

Lloyd's Register  
Foundation

W1336-0066

Items:—

Renewed ...

Removed and Faired or Repaired ...

Faired or Repaired in place ...

PRESENT CONDITION OF THE

Stringers

Dbing Plates under Sounding Pipes

Copper, or Y.A.  
(State if