

F.E.

of Ship Surveyor _____

Received from Chief Ship Surveyor _____

AME Steel S.S. "AYANT GARDE" Rpt. Hul. No. 32354

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.

Course No. 48.0 Depth "d" 14.17

Fig: Table No. 3 Description Bulb Angle

Longitudinal No. 9600

Proportions $\frac{\text{Length}}{\text{Depth}} = 12.5$

~~Bulb~~ Sheerstrake as approved

This vessel appears to have been built in accordance with the approved plans, and it is submitted she is eligible to be classed 100 A-1. (steel) "Stm. Trawler" as recommended.

1 Dk.

DB & Bunkers 35' 53". APT 96.

BK 8". 4 BH. Cem. Wlgh's A+C.P. @ 96'. F 32'.

Date of Build 10, 20.

M
AES
29-12-20



© 2021

Lloyd's Register Foundation

W1358-0284