

total capacity tons. FPT tons; APT tons; M1 feet

CHARACTER.
X for Special Survey.
Date of last Survey and of
Periodical Surveys.

Machinery and
Survey
(including date of

1m,10,30.

1

Sent to Chief Surveyors

Received from Chief Surveyors

15 FEB 1940

VESSEL'S NAME "FRISCO".

Report Lon.

No. 108282a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey

When due

The class is subject to missing rivets in 2 frames, to floor in forward tank being fitted at the first opportunity.

The 3rd Special Survey No.2, due 3,39 has been partly held.

The Genoa Surveyors now write enclosing a free translation of a letter from the Owners intimating withdrawal of the vessel's class.

It is submitted the class of the vessel be withdrawn from the Register Boock and Three Dots(...)inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw class

Insert ...

Handwritten signature
14.2.40.



© 2021

Lloyd's Register
Foundation

W1351-0140

W1351-0142