

w1356-0124

1m,821.

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Steel S.S. "Zembra"* Rpt. *Bmn* No. *670*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. *80.7* Depth "d" *21.54'*  
 Framing: Table No. *2* Description *Bult angle as*  
 Longitudinal No. *29965* *approved.*  
 Proportions  $\frac{\text{Length}}{\text{Depth}} = \frac{12.4}{1}$   
~~Deck~~ Sheerstrake *as approved.*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *100.A.1. (Steel) "cantilever framed "Topside Tanks". 1 Dk (stl), 2<sup>nd</sup> Dk (stl) in No. 1 Hold. "Longitudinal Framing at Double Bottom and Deck." Cell DB 311' 1835t, DTf 26' 154t, FPT 139t, APT 194t, Topside Tanks 324t, 3 after tanks 118t, Transverse Topside Tanks 344t. FK, 7BH, Cem, Lloyds CP, P108, F29, Mch. Aff.*

© 2021  
 Lloyd's Register  
 Foundation  
 A.W.J.  
 20/10/23