

COPY.

Lloyd's Register of Shipping.



Hamburg Report Nr. 23081

Port of Hamburg

22nd February, 1939

This is to Certify that I have

Surveyed the Boiler and Machinery of the Steel Sc. "SUND",
517 tons gross of Hamburg, afloat and in dry dock at Hamburg
for the Requirements of L.M.C. and examination of Tail shaft

and that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report stating that all
recommendations made by me in connection therewith have
been carried out to my satisfaction, and that I have

Recommended that the record of L.M.C. -2.39 and Tail
shaft (0.3.) seen -2.39. xx

be made in the Register Book in the case of this vessel.

Friedrich H.
Engineer Surbeyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



Lloyd's Register
Foundation

W1358-0158