

1

Sent to Chief Surveyors 23/2/08

Received from Chief Surveyors

VESSEL'S NAME *Sol. S. Agnes Ellen*

Report *Gb.*

No. *24286*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." — Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

First Entry

When due

+100 A.I. ("Steel")

1 D^o ("Steel") 'Well dk'

W.B. = F.P.T. 41t A.P.T. 3t.

BK 7" 3 B.H. Cem. Lloyds Q & C.P. Q46' B10' F23' Mchly aft.

Roc
23/2/08

C.A.P.



© 2021

Lloyd's Register
Foundation

W1363 - 0103

" Spacing
PILLARS, In ~~tween Decks~~ Size and Spacing

42

42

" Tie Plates

" Deck, Material and thickness

7.72

5 x 2 1/2