

## REPORT of SURVEY for REPAIRS, &amp;c.

Date of writing Report 19 When handed in at Local Office 19 Port of

No. in Reg. Book. Survey held at Date, First Survey Last Survey (No. of Visits)

199 on the Wood, Iron or Steel ship "Agnes" Master  
TONNAGE:— Built at Rowhedge, Essex By whom Doyland Shipyard Ltd When 1902 - 1  
GROSS 60 Owners Cape Copper Co Ltd Port belonging to London  
UNDER DK. 54  
NET 60 Owners' Address  
(If not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage  
WB=CellDBorDBa feet; uE&B feet; f feet; }  
total capacity tons. FPT tons; APT tons; MT feet tons. }  
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.  
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 64062 Port Lon  
(Periodical Surveys, when held, must be reported in detail and serialim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)  
CHARACTER.  
\* for Special Survey.  
Date of last Survey and of Periodical Surveys.  
Years Assigned now expired.  
Machinery and Boiler Surveys (including date of N.B., if any).  
- 12 A -  
Barge for being towed  
harbour purposes  
2.02  
CF. F&C 11.01  
9712 yrs. Mat.  
Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? also whether any damage report was made, and, if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS :—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
Renewed ... ..								
Removed and Fair'd or Repaired ... ..								
Fair'd or Repaired in place ... ..								

PRESENT CONDITION OF THE	Stringers .....	Dbing. Plates under Sounding Pipes.....	Copper, or Y.M. of Wood Vessels..... (State if on Felt.) When put on, Month..... Year.....
Decks .....	Inner Bottom Plating.....	Engine Room Skylights.....	Boats.....
Caulking of Decks.....	State if Tanks have been examined inside .....	Coal Bunkers, Open'gs, Lids, &c.....	Masts, Yards, &c.....
Waterways.....	State if Tanks now tested.....	Scuppers .....	Condition, how ascertained..... (State if wedges removed)
Coamings .....	Bulkheads .....	Cargo Hatchways .....	Sails .....
Beams & Fastenings .....	Ceiling.....	Hatches .....	Equipment letter .....
Outside Plating .....	Cement or Asphalt .....	Planking of Wood Vessels.....	Anchors, No. of .....
Caulking of ditto.....	(State which.) Rudder .....	Caulking ditto.....	Cables (State if now ranged).....
Rivets .....	Steering gear and its connections .....	Treenails ditto.....	„ length..... size..... (on board)
Breasthooks & Crutches.....	Windlass .....	Breasthooks & Stemson ditto.....	„ Rule length..... size..... (per Table 22)
Transoms.....	Have Pumps now been examined and found efficient? .....	Transoms, Pointers, & Crutches ditto.....	Hawser & Warps.....
Frames.....	Have Sluice Valves now been examined and found efficient? .....	Timbers of Frame at openings ditto.....	Standing & Running Rigging.....
Reverse Frames.....	Have Watertight Doors now been examined and found efficient? .....	Ditto ditto at other places ditto.....	
Floors.....		Stringers, Clamps & Shells ditto.....	
Keelsons.....		Salting ditto..... (State if examined.)	

## General Observations, Opinion as to Class, Recommendation, &amp;c. :—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus for example :—“to remain as now classed in the Register Book without fresh record of Survey,” “to remain as classed and to have record of survey, 1,07,” or “to remain as classed and to have record of survey, 1,07, and the notations of ss No. 1-07 and ptND07, &c.”

Survey Fee (per Section 28) ..... £  
Special Damage or Repair Fee (if any) ..... £  
Travelling Expenses (if chargeable) ..... £  
Second Surveyor's Fee (if any) ..... £  
Fees applied for, ..... 19  
Received by me, ..... 19

Committee's Minute

Character Assigned

JUL 7 APL 1906

Surveyor to Lloyd's Register of British &amp; Foreign

Lloyd's Register Foundation