

EL'S NAME *3/5 "WILLEMSPLEIN"* Report *Rotterdam* No. *23824*<sup>a</sup>

THICKNESSES OF PLATING ascertained by drilling, and comparison of same with the original thicknesses.

The thicknesses are in *millimeters*  
of an inch.

STRAKE.	AMIDSHIP.						FORWARD.						AFT.						REMARKS.
	Original Thickness.	Thickness by drilling.		Diminution if any.		Original Thickness.	Thickness by drilling.		Diminution if any.		Original Thickness.	Thickness by drilling.		Diminution if any.					
		Port.	Std.	Port.	Std.		Port.	Std.	Port.	Std.		Port.	Std.	Port.	Std.	Port.	Std.		
DECK STRAKE	17 1/2	18	18				11	10	11	1	-	9 1/2	10	9		1/2	The general condition of the vessel's plating found good edges and bulks not wasted.		
below	16 1/2	17	17	-	-		11	11	10	-	1	9 1/2	9	9	1/2	1/2			
DECK STRAKE	16	16	16	-	-		11 1/2	12	13			11 1/2	13	13	-	-			
below	16	15	16	1	-		11 1/2	13	13			11 1/2	13	13	-	-			
"	15	15	15	-	-		11	13	14			11	12	13	-	-			
"	15	16	16	-	-		11	13	13			11	12	12	-	-			
"	15	16	16	-	-		11	12	12			11	12	13	-	-			
"	15	15	15	-	-		11	11	11			11	12	15	-	-			
"	15	16	18	-	-		12	13	11			12	13	14	-	-			
"							12	12	12			12	11	12	1	-			
"							12	15	15			12	13	12	-	-			

© 2020

Lloyd's Register

Drillings at ends to be made in the vicinity of the peak bulkheads.

Lloyd's Register  
Foundation

W137-0027