

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME Stl S. M.V. "WOENS DRECHT" Rpt. Rpt No. 15002

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/02.)

Transverse No. 81 Depth "d" _____

Framing: Table No. ✓ Description Channels & hull angles

Longitudinal No. 29970 as approved.

Proportions $\frac{\text{Length}}{\text{Depth}} =$ 13.21

Deck Sheerstrake as approved

old Rules

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✚ 100 A. I. (Steel) "Carrying petroleum in bulk"
2 Dks (Stl) "Longitudinal framing at bottom and at decks"
Cell D.B. & E 64' 137t, F.P.T. 150t, A.P.T. 66t.
F.K, 16 B.H., pt km, Lloyds A & CP.
P 99' F 33 "machy aft"



Lloyd's Register Foundation

W137-0172

[Handwritten signature]
2020 1.4.26