

(2m.11.5.)

1.

Sent to Chief Surveyors *23.4.07*

Received from Chief Surveyors

VESSEL'S NAME *Ste. S. S. "Chikuzen Maru"* Report *Sl. No. 25147*

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey *Trit entry* When due

*+ 100 A 1 ("Steel") Spar Deck*

*1 DR (Ste) + open DR (Ste) + deep framing.*

*N.B - Cell DB a 92' in E + B 52' f 114' 500E FPT 34E APT 24E*

*FK 6BH Plyd A4CP P33' B90' F39'*

*C. J. J.  
23/4/07*



© 2021

Lloyd's Register  
Foundation

Plate on Tee Bulb  
Angles on upper edge

Flue Plates  
Deck Material and thickness