WB=CellDBorDBa ____ feet; uE&B ____ feet; f ____ feet;
total capacity ____ tons. FPT ____ tons; APT ____ tons; MT ____ feet ____ tons.

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Particulars of Classificat
precisely as in Registe

CHARACTER.
✠ for Special Survey.
Date of last Survey and of Periodical Surveys.

100A1
fishing pur
5.11

board (if assigne
Ship and now ve

rvices for this
m?

r Items :—

Copper, or Y.
(State if
When put
Boats
Masts, Yards
Condition, how
(State if
Sails
Equipment
Anchors, No.
Cables (Stat
„ length
(on
„ Rule le
Hawser & W
Standing &

vessel in the Reg
"to remain as cl

1,13.

# POSTPONED SURVEYS.

Case of the Steel s.s. "Coreopsis"

o. 1658 in Reg. Bk. 88/39 tons, Built 1911-5 mo.

lassed ✠ 100 A 1. Owners P. Gardiner
for fishing purposes. Port of Registry Kirkcaldy
5.11.

✠ LMC 5.11.

rvey due Screw Shaft Survey due May, 1913

The Owner's Agents state they have been authorised by the Owner to say that he has no intention of continuing the classification of this vessel.

They add that the shaft is drawn every two years for examination for insurance purposes. CH 30.6.13.

It is submitted that the vessel's class be withdrawn from the Register Book and ... inserted in Red Ink indicating withdrawal of class at Owners request.

R.S. 30.6.13.

mmittee's Minute TUE. JUL. 1 - 1913

cision Withdraw Class
+ insert ...

W1414-0058
W1414-0059

© 2021
Lloyd's Register
Foundation

For approv
See "L122