

Received by Chief Ship Surveyor 19.8.16

Received from Chief Ship Surveyor _____

VESSEL'S NAME Steels Yamagata Maru Rpt. Kag No. 1075

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 79.08

Depth "d" 17.5

Framing: Table No. 3 page

Description Bulb angle as approved

Longitudinal No. 27282

Proportions Length = 11.86
Depth = _____

Upper Deck Sheerstrake as approved.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100 A-1 (Steel) as recommended.

100 A-1 (Steel)

2 AK (Steel)

CCDB 294 772 E. a PT. 27 E.

FK. 6BH Can. Lat. P. 33. B 74 F 40



2020
198

Lloyd's Register
Foundation