

Under Upper Dk.

Depth, at middle of length from top of keel to top of

22-8

Chief Ship Surveyor 31/5/11

Received from Chief Ship Surveyor _____

'S NAME Stl. S. S. "St. Petersburg" Rpt. Cpu. No. 3369.

69.

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey 1st Entry & Damage.

No. 96

The first entry report on this vessel was before the Committee on the 30th May, when the vessel was classed*100A1 "Awning Deck with freeboard", subject to some damage, which had been sustained when the vessel was being launched, being made good to the Copenhagen Surveyors satisfaction.

A telegram has now been received from the Copenhagen Surveyors stating that the repairs have been carried out in a satisfactory manner and that the fees have been paid.

It is submitted the vessel appears worthy to remain classed without special conditions.

ow. } without special condition.

RM
31/5/11

M



© 2021

Lloyd's Register Foundation

w/1430-0015

w/1430-0017

W *31/5/11*