

assure himself of the thorough efficiency of those parts of each Boiler?

5.5 "bolores"

Submitted the Barcelona Surveyor
be communicated with by wire & instructed
to reply by wire to the Sec'y Letter of 1. July 15
and state if the 5.5 hr's in the hull of
this vessel was advanced or completed
at Barcelona and if so forward his
report without further delay.



W1438-0020

and other valves water gauge fittings and test