

F.E.

Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor \_\_\_\_\_

S NAME

*Shess Kilchattan*

Rpt.

*101*

No.

*30799*

emarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

nsverse No. *46.33*

Depth "d" *15.0*

ming: Table No. *✓*

Description

*Build angle as approved*

gitudinal No. *7876*

Proportions  $\frac{\text{Length}}{\text{Depth}} = 10.3$

Deck Sheerstrake

*& other scantlings as approved for*

*the A-1. class*

This vessel appears to have been built in accordance with the  
les and the approved plans, and it is submitted she is eligible to  
classed ✕ A-1 (Steel) for Government Service as set

*10x (Steel)*

*Cell 5.B. in E 26. 201.*

*FK. Y.B.H. pl cen. Lloyds and*

*Date of Build 10.18.*



© 2021

Lloyd's Register  
Foundation

*W1454 0119*