

1

(....) 60-42.

Sent to Chief Surveyors 2-2-18

Received from Chief Surveyors

VESSEL'S NAME Steel % Hisko Report Phe No. 2710

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey 1<sup>st</sup> Entry When due

+ 100 A1 (Steel)

Fitted with cylindrical tanks for carrying petroleum.

1 1/2" (Steel)

Cell WB 350' 1611E. FPT 115E. APT 144E.

FK 10 BH. A+CP. P99' B27' F50' Mch'y aft.

Date of Build 10.17



© 2021 MEI.

4.2.18

Lloyd's Register  
Foundation

W1466-0087