

nt to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME *Steel P.C. BAHADUR*

Report *Joh
G.H.*

No. *19089
48228*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report 24/5/92.)

ature of Survey *1st Entry*

When due *Revised Rules*

+ 100 A-1. (Steel)

2 DKS (Steel)

Cell DB 348' 1186t, DTA 35' 981t, FPT 118t, APT 31t.

FK. "Intermediate Tween D^k BH in after hold dispensed with"

5 BH to Upper D^k 1 BH to 2nd D^k, Jt Cem, Lloyd's A+CP

P 40', B 121', F 41'

W147-0191



© 2021

Lloyd's Register
Foundation

*W147
12.9.28*