

Was a damage report made by anyone else? If so, by whom?

W1147-0196

Pahadur.

No. 49587.  
Off. 48228.

It is submitted that  
this vessel is eligible for  
THE RECORD.

7 Dec 8.29 F.D. C.L.

It is concluded that the Centre back  
tube plates are not less than  $1\frac{13}{16}$   
as shewn on the approved plan  
of main Boilers but this should be  
confirmed.

Dec 17/9/29.

Ri

R. J. J.

12/9/29.

Lloyd's Register  
Foundation