

Received by Chief Ship Surveyor _____


Received from Chief Ship Surveyor _____

VESSEL'S NAME Steel S.S. "BUSHO MARU" Rpt. Kob No. 3183

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)



Transverse No. 65.5 Depth "d" 11.92Framing: Table No. 3 Description Bull-angLongitudinal No. 18634Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{9.33}{1}$ May Deck Sheerstrake as approved

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed  100-A-1. (Steel) as recommended

2 Dks (Steel 0.15)

Cell DB 240' 624t, ITa 18' 232t, FPT 36t, APT 42t

FK, 5BH, Cen, Av CP. P45' 6100' F34'


3-8-21

© 2021

Lloyd's Register
Foundation

W1471-0194