

2300, 12, 19.

*Disclaimed Bot*  
*47*

By Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME *Steel S.S. "JOHN JAY"*Report *Phl.*No. *3863*

## For the CHIEF SHIP SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.5.02.)

Nature of Survey

When due

*100 A 1. (steel) "Shelter Dk with freeboard"*  
*1 Dk (steel) & Shelter Dk (steel), and 2<sup>nd</sup> Dk. (steel) forward.*

*Webframes. Longitudinal Framing.*

*Cell DB 344' 1364 t. MT 24' 946 t. DTA 21' 153 t. FPT 235 t. APT 174 t.*

*Ex 6 BH to Shelter Dk 2 BH to upper Dk. pl. Cern. ATCP.*

*P 41', B 134', F 46' on Shelter Dk.*

*c/o*  
*20.8.20*

*APB.**22-7-20*

*It is concluded the <sup>readable</sup> ~~width~~ of Rudder Post is as required but the Surveyor should be requested to state if this is so*

W1481-0098

Corresponding Draught

*28* ft. *5* ins.

Freeboards compared and found correct