

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Single Sc. "BHIMA" Report Gls. No. 60930**For the CHIEF SHIP SURVEYOR, and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

FIRST ENTRYWhen dueC.S.S. Vessel with Tonnage Opening.

100AL "With Freeboard"

1 Dk. &amp; Shelter Dk. ✓

Cell. DB 353' 1365t, FPT 192t, APT 260t.

FK, One intermediate BH dispensed with (Coll. BH to Sh. Dk., 5BH to 2nd Dk.)

F 34'

LAQCP

O.L. 431.5'.

*[Signature]* *[Signature]*  
18:4:39.



© 2019

Lloyd's Register  
Foundation

W149-0148