

## REPORT of SURVEY for REPAIRS, &amp;c.

Date of writing Report 7th Sept. 1907 When handed in at Local Office 7th Sept. 1907 Port of Newcastle-on-Tyne  
 No. in Survey held at South Shields Date, First Survey 4 Last Survey Sep. 5<sup>th</sup> 1907  
 eg. Book. 680 on the Wood, Iron or Steel S. G. "LORD CHARLES BERESFORD" Master A. Goldspink.  
 TONNAGE:— Built at Selby By whom Cochran & Sons When 1904 —  
 GROSS 10081 Owners Lowestoft Steam Towing Drifters Co. Ltd. Port belonging to Lowestoft  
 UNDER DE. 74 Owners' Address  
 NET 16 (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Dry Dock Name of Dock Smiths. Destined Voyage

WB=CellDBorDBa feet; uE&B feet; f feet; }  
 total capacity tons. FPT tons; APT tons; MT feet tons. }

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.  
 If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. Port

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

CHARACTER.  
 \* for Special Survey.  
 Date of last Survey and of Periodical Surveys.  
 Year assigned now expired.  
 Machinery and Boiler Surveys (including date of N.B., if any).  
+ 100A1 4.07  
for fishing purposes.  
(See plates) + 100A 4.07

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? also whether any damage report was made, and, if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Docking

Vessel placed in dry dock. the bottom keel and rudder cleaned examined and coated.

## SUMMARY OF DAMAGE REPAIRS:—

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

## PRESENT CONDITION OF THE

	Good	Good	Good	Good	Good	Good	Good	Good
Decks								
Caulking of Decks								
Waterways								
Coamings								
Beams & Fastenings								
Outside Plating								
Caulking of ditto								
Rivets								
Breasthooks & Crutches								
Transoms								
Frames								
Reverse Frames								
Floors								
Keelsons								
Stringers								
Inner Bottom Plating								
State if Tanks have been examined inside								
State if Tanks now tested								
Bulkheads								
Ceiling								
Cement or Asphalt (State which.)								
Rudder								
Windlass								
Have Pumps now been examined and found efficient?								
Have Steam Valves now been examined and found efficient?								
Have Watertight Doors now been examined and found efficient?								
Double Plates under Sounding Pipes								
Engine Room Skylights								
Cool Bunkers, Open'gs, Lids, &c.								
Scuppers								
Cargo Hatchways								
Hatches								
Planking of Wood Vessels								
Caulking ditto								
Treenails ditto								
Breasthooks & Stemson ditto								
Transoms, Pointers, & Crutches ditto								
Timbers of Frame at openings ditto								
Ditto ditto at other places ditto								
Stringers, Clamps & Shelves ditto								
Salting ditto (State if examined.)								
Copper, or Y.M. of Wood Vessels (State if on left.)								
When put on, Month Year								
Boats								
Masts, Yards, &c.								
Condition, how ascertained								
(State if wedges removed)								
Sails								
Equipment letter								
Anchors, No. of								
Cables (State if now ranged)								
" length (on board) size								
" Rule length (per Table 22) size								
Hawsers & Warps								
Standing & Running Rigging								

## General Observations, Opinion as to Class, Recommendation, &amp;c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c."

This vessel, as far as seen, is eligible in my opinion to have class as contemplated.

Office Fee (if chargeable) per Scale II, Sec. 27	£	:	:	Fees applied for,
Survey Fee (per Section 24)	£	:	:	19
Special Damage or Repair Fee (if any) (per Sec. 28.)	£	:	:	Received by me,
Travelling Expenses (if chargeable)	£	:	:	19
Second Surveyor's Fee (if any)	£	:	:	

Committee's Minute

Character Assigned

FRI. 18 OCT 1907

100A1  
for fishing purposes

Surveyor to Lloyd's Register of British & Foreign Shipping.



© 2021

Lloyd's Register  
 Foundation