

Request ~~EXHIBIT~~ { Mont Carmel }  
~~100 class 1905~~

F.E.

Received by Chief Ship Surveyor 31. 8. 05

Received from Chief Ship Surveyor

VESSEL'S NAME St. S. S. Phoenix

Rpt. Hull No. 17135

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.

CLASSIFICATION. N.N. KARDAMILA

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<u>2/20"</u>	<u>Proportions</u>
Spar Sheerstrake . .		
Description of Framing:— <u>Deep framing.</u> (viz., ordinary, deep, zed, channel or bulb-angle).		DISCLOSED SECTION. No. <u>74</u>

The chain cable on <sup>no. 46.</sup> 2-23, or .16 of one per cent, less in weight than required by Table 22 for the rule length of 270 fathoms.

In other respects This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ± 100 A 1 ("Steel") as recommended.

± 100 A 1 ("Steel")

2 DRs (1 Stl & 1 1/2 In & 1/2 Stl) & deep framing.

W. B = Cell DB a 88' x E 20' f 152' 775t APT 28t

FK 68H Cam. Plydi A & CP P31' B110' F32'



© 2004  
31/8/05

Lloyd's Register Foundation

W1532-0128