

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

13. 3. 23

VESSEL'S NAME **Steel s.s. "KASPAR"**Report **Lon.**

No. 86419A

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey _____

When due _____

The Hamburg Surveyors forward a letter from the Owner stating that this vessel is now classed with Germanischer Lloyd, and it is not desired to maintain her classification with this Society.

It is submitted the vessel's class be withdrawn from the Register Book and three dots(...) inserted in lieu, indicating withdrawal of class at Owner's request.

Withdraw class

Insert. (...)

