

## REPORT of SURVEY for REPAIRS, &amp;c.

Date of writing Report.....10.....When handed in at Local Office.....10.....

Port of

Liverpool

No. in Survey held at  
Reg. Book.

Date, First Survey

Last Survey

19

1031 on the Wood, Iron or Steel

Primrose

Master

YEAR.

MONTH.

TONNAGE:-

Built at

Paisley

By whom

J. Tullerton &amp; Co.

When 1910

4

GROSS

611

Owners

R. Hughes &amp; Co.

Port belonging to

Liverpool

UNDER DEK.

419

Owners' Address

(if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock?

Name of Dock

Destined Voyage

No.

CB=CellDBorDBa

feet; uE&amp;B

feet; f

feet; }

Total capacity

tons. FPT

tons; APT

tons; MT

feet

tons.

Particulars of Classification (which must be inserted precisely as in Register Book &amp; Supplements).

CHARACTER.  
X for Special Survey.  
Date of last Survey and of  
Periodical Surveys.Year  
Assigned  
now  
expired.Machinery and Boiler  
Surveys  
(including date of N.B., if any).+ 100A 1.  
1.14

+ LMC 1.14

20. Nov 14.

T. 5.13

Last Report, No.

7165

Port Liv

Repairs, when held, must be reported in detail and serially in the terms of the Rules. State clearly the nature, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; being detailed in the body of the report, should be summarised in the form shown below. Whenever the of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on this form. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if assigned) as  
painted on Ship and now verified } ft. ins.

Cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were

Was a damage report made by anyone else? If so, by whom?

OR EXAMINATION AS PER RULE, FOR

OF DAMAGE REPAIRS :—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
ed								
ed and Fair'd or Repaired								
or Repaired in place								
CONDITION OF THE	Stringers	Dbing. Plates under Sounding Pipes				Copper, or Y.M. of Wood Vessels		
	Inner Bottom Plating	Engine Room Skylights				(State if on Felt.)		
	State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.				When put on, Month Year		
	State if Tanks now tested	Scuppers				Boats		
	Bulkheads	Cargo Hatchways				Masts, Yards, &c.		
	Ceiling	Hatches				Condition, how ascertained		
	Cement or Asphalt	Planking of Wood Vessels				(State if wedges removed)		
	(State which.)	Caulking ditto				Sails		
	Rudder	Treenails ditto				Equipment letter		
	Steering gear and its connections	Breasthooks & Stemson ditto				Anchors, No. of		
	Windlass	Transoms, Pointers, & Crutches ditto				Cables (State if now ranged)		
	Have Pumps now been examined and found efficient?	Timbers of Frame at openings ditto				„ length size		
	Have Sluice Valves now been examined and found efficient?	Ditto ditto at other places ditto				(on board)		
	Have Watertight Doors now been examined and found efficient?	Stringers, Clamps & Shelves ditto				„ Rule length size		
	(State if examined.)	Salting ditto				Hawser & Warps		
		(State if examined.)				Standing & Running Rigging		

## General Observations, Opinion as to Class, Recommendation, &amp;c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon survey, thus for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

Survey Fee (per Section 99) £

Special Damage or Repair Fee (if any) £

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

Fees applied for,

10


Received by me,

10

Committee's Minute

Character Assigned

Surveyor to Lloyd's Register of Shipping.

Lloyd's Register  
Foundation

WISS3-0060