

REPORT ON ^{Part} MACHINERY

No. 3338a

Received at London Office

SAT. FEB. 21. 1914

WED. MAR. 25. 1914

of writing Report 20th July 1914 When handed in at Local Office Dublin 19 Dublin Port of Dublin

in Survey held at Dublin Date, First Survey 15th Jan'y Last Survey 6th July 1914

eg. Book. S.S. "Streatham" (Number of Visits 6)

on the S.S. "Streatham" Tons ^{Gross} _{Net}

Master Built at Dublin By whom built Dublin Dockyard Co. Ld When built

Engines made at By whom made when made

Boilers made at By whom made when made

Registered Horse Power Owners Port belonging to

nom. Horse Power as per Section 28 Is Refrigerating Machinery fitted for cargo purposes Is Electric Light fitted

ENGINES, &c.—Description of Engines

No. of Cylinders No. of Cranks

Dia. of Cylinders Length of Stroke Revs. per minute Dia. of Screw shaft as per rule Material of screw shaft as fitted

Is the screw shaft fitted with a continuous liner the whole length of the stern tube Is the after end of the liner made water tight

the propeller boss If the liner is in more than one length are the joints burned If the liner does not fit tightly at the part

between the bearings in the stern tube, is the space charged with a plastic material insoluble in water and non-corrosive If two

eners are fitted, is the shaft lapped or protected between the liners Length of stern bush

Dia. of Tunnel shaft as per rule Dia. of Crank shaft journals as per rule Dia. of Crank pin Size of Crank webs Dia. of thrust shaft under

rollers Dia. of screw Pitch of Screw No. of Blades State whether moveable Total surface

No. of Feed pumps Diameter of ditto Stroke Can one be overhauled while the other is at work

No. of Bilge pumps Diameter of ditto Stroke Can one be overhauled while the other is at work

No. of Donkey Engines Sizes of Pumps No. and size of Suctions connected to both Bilge and Donkey pumps

in Engine Room In Holds, &c. 6-2 1/2" - 1.4" x 4-5" etc.

No. of Bilge Injections sizes Connected to condenser, or to circulating pump Is a separate Donkey Suction fitted in Engine room & size

Are all the bilge suction pipes fitted with roses Are the roses in Engine room always accessible Are the sluices on Engine room bulkheads always accessible

Are all connections with the sea direct on the skin of the ship yes Are they Valves or Cocks both

Are they fixed sufficiently high on the ship's side to be seen without lifting the stokehold plates Are the Discharge Pipes above or below the deep water line above

Are they each fitted with a Discharge Valve always accessible on the plating of the vessel yes Are the Blow Off Cocks fitted with a spigot and brass covering plate yes

What pipes are carried through the bunkers None How are they protected inside tank

Are all Pipes, Cocks, Valves, and Pumps in connection with the machinery and all boiler mountings accessible at all times

Are the Bilge Suction Pipes, Cocks, and Valves arranged so as to prevent any communication between the sea and the bilges

Dates of examination of completion of fitting of Sea Connections 6th July of Stern Tube 20th Jan'y Screw shaft and Propeller 23rd Jan'y

Is the Screw Shaft Tunnel watertight Is it fitted with a watertight door worked from

OILERS, &c.—(Letter for record) Manufacturers of Steel

Total Heating Surface of Boilers Is Forced Draft fitted No. and Description of Boilers

Working Pressure Tested by hydraulic pressure to Date of test No. of Certificate

Can each boiler be worked separately Area of fire grate in each boiler No. and Description of Safety Valves to

each boiler Area of each valve Pressure to which they are adjusted Are they fitted with easing gear

Smallest distance between boilers or uptakes and bunkers or woodwork Mean dia. of boilers Length Material of shell plates

Thickness Range of tensile strength Are the shell plates welded or flanged Descrip. of riveting: cir. seams

long. seams Diameter of rivet holes in long. seams Pitch of rivets Lap of plates or width of butt straps

Per centages of strength of longitudinal joint rivets Working pressure of shell by rules Size of manhole in shell

plate

Size of compensating ring No. and Description of Furnaces in each boiler Material Outside diameter

Length of plain part top Thickness of plates crown Description of longitudinal joint No. of strengthening rings

bottom

Working pressure of furnace by the rules Combustion chamber plates: Material Thickness: Sides Back Top Bottom

Pitch of stays to ditto: Sides Back Top If stays are fitted with nuts or riveted heads Working pressure by rules

Material of stays Diameter at smallest part Area supported by each stay Working pressure by rules End plates in steam space:

Material Thickness Pitch of stays How are stays secured Working pressure by rules Material of stays

Diameter at smallest part Area supported by each stay Working pressure by rules Material of Front plates at bottom

Thickness Material of Lower back plate Thickness Greatest pitch of stays Working pressure of plate by rules

Diameter of tubes Pitch of tubes Material of tube plates Thickness: Front Back Mean pitch of stays

Pitch across wide water spaces Working pressures by rules Girders to Chamber tops: Material Depth and

thickness of girder at centre Length as per rule Distance apart Number and pitch of stays in each

Working pressure by rules Superheater or Steam chest; how connected to boiler Can the superheater be shut off and the boiler worked


separately Diameter Length Thickness of shell plates Material Description of longitudinal joint Diam. of rivet

holes Pitch of rivets Working pressure of shell by rules Diameter of flue Material of flue plates Thickness

If stiffened with rings Distance between rings Working pressure by rules End plates: Thickness How stayed

Working pressure of end plates Area of safety valves to superheater Are they fitted with easing gear

W156-0119



VERTICAL DONKEY BOILER— Manufacturers of Steel

No. _____ Description _____
 Made at _____ By whom made _____ When made _____ Where fixed _____
 Working pressure tested by hydraulic pressure to _____ Date of test _____ No. of Certificate _____ Fire grate area _____ Description of Safety
 Valves _____ No. of Safety Valves _____ Area of each _____ Pressure to which they are adjusted _____ Date of adjustment _____
 If fitted with easing gear _____ If steam from main boilers can enter the donkey boiler _____ Dia. of donkey boiler _____ Length _____
 Material of shell plates _____ Thickness _____ Range of tensile strength _____ Descrip. of riveting long. seams _____
 Dia. of rivet holes _____ Whether punched or drilled _____ Pitch of rivets _____ Lap of plating _____ Per centage of strength of joint _____ Rivets _____ Plates _____
 Working pressure of shell by rules _____ Thickness of shell crown plates _____ Radius of do. _____ No. of stays to do. _____ Dia. of stays _____
 Diameter of furnace Top _____ Bottom _____ Length of furnace _____ Thickness of furnace plates _____ Description of joint _____
 Working pressure of furnace by rules _____ Thickness of furnace crown plates _____ Radius of do. _____ Stayed by _____
 Diameter of uptake _____ Thickness of uptake plates _____ Thickness of water tubes _____ Dates of survey _____

SPARE GEAR. State the articles supplied:—

The foregoing is a correct description,

Manufacturer.

Dates of Survey while building { During progress of work in shops - - }
 { During erection on board vessel - - - }
 Total No. of visits _____

Is the approved plan of main boiler forwarded herewith

Dates of Examination of principal parts—Cylinders _____ Slides _____ Covers _____ Pistons _____ Rods _____
 Connecting rods _____ Crank shaft _____ Thrust shaft _____ Tunnel shafts _____ Screw shaft _____ Propeller _____
 Stern tube _____ Steam pipes tested _____ Engine and boiler seatings _____ Engines holding down bolts _____
 Completion of pumping arrangements _____ Boilers fixed _____ Engines tried under steam _____
 Main boiler safety valves adjusted _____ Thickness of adjusting washers _____
 Material of Crank shaft _____ Identification Mark on Do. _____ Material of Thrust shaft _____ Identification Mark on Do. _____
 Material of Tunnel shafts _____ Identification Marks on Do. _____ Material of Screw shafts _____ Identification Marks on Do. _____
 Material of Steam Pipes _____ Test pressure _____

General Remarks (State quality of workmanship, opinions as to class, &c.)

The Stern Post has been bored & the tube fitted, also the Sea Cocks. The screw shaft & screws & Thrust shafts are in place. The vessel was towed from this port to Glasgow for completion of Machinery. Glasgow Surveyors notified.

Certificate (if required) to be sent to _____
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)


The amount of Entry Fee .. £	:	:	When applied for,
Special £	:	:19.....
Donkey Boiler Fee £	:	:	When received,
Travelling Expenses (if any) £	:	:19.....

MacWilliam
 Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.
 at Dublin

Committee's Minute

MAR. 27. 1914

Assigned



© 2019

Lloyd's Register Foundation