



GENERAL REMARKS (State quality of workmanship, opinions as to class, &c.)

Spare Gear

- 1/2 Crank Shaft
 1 Propeller Shaft, 2 propeller blades; set studs & nuts set?
 2 Pair Crank pin bushes
 4 Set top end braces.
 2 Slide valve spindles
 2 Quadrant bushes
 Set piston rings for each cylinder (one engine)
 2 Set packing rings each piston valve.
 2 Eccentric Straps complete
 Air pump rod, bucket, leak valve & guards set?
 3 Cylinder escape valve springs
 2 Safety valve springs
 Set valves & seats for job, bulge & auxiliary pumps
 Spare fan engine complete
 Centrifugal Pump, crank shaft, impeller & shaft, set?
 and all gear to Lloyd's Rules Extra

Donkey Pumps

- 1 Weir General $11\frac{1}{2} \times 15\frac{1}{2} \times 26$
 1 Lamonts Aux. Feed. $5 \times 3\frac{1}{2} \times 6$ Duplex
 1 - Ballast $9 \times 11 \times 10$
 1 Weir Feed $11\frac{1}{2} \times 15\frac{1}{2} \times 26$ Double
 1 Lamonts Fire $8 \times 5\frac{1}{2} \times 8$ Duplex
 2 - Fresh Water $4 \times 4 \times 5$
 1 Clark Chapmans Ash Cy. $12 \times 7\frac{1}{2} \times 10$


Certificate (if required) to be sent to the Committee's Minute.

The amount of Entry Fee...	£	:	:	When applied for.
Special	£	:	:	19
Donkey Boiler Fee ...	£	:	:	When received.
Travelling Expenses (if any) £	:	:	:	19

Committee's Minute

Assigned

TUES. NOV 27 1906


 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2021

Lloyd's Register
Foundation

These pages

Signal Letter

Official

/ 2

No., Date, and

Whether British or Foreign Built

British

Number of

Number of

Rigged

Stern

Build

Galleries

Head

Framework

Lock - vessel

700 - Number of

50 - Number of

52 - and their

103

110

115

108

26

64

53

32

68

23

Two

sets

Under Tonnage

Closed-in

Space of

Forecas

Round

Other

chan

Spaces for

Section

1894, i

Deduction

No. of

Name, R

Br

Dec

The

Dated

W B &