

KEELSONS AND STRINGERS.

3m, 3.21.

ent to Chief Surveyors

Received from Chief Surveyors

ESSEL'S NAME *Stut S. S. "CHILWA"*

Report

No. 41698

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ature of Survey

When due

\* 100. A-1. (Stut) "Shade Dk"

2 Dks (upper Stut-ws) ✓ Shade deck (Stut teak.s.)

Cell Dk. 342' 752t, ITa 47' 775t, Tanks between tunnels 47' 74t.

Tanks at Sides of tunnel 23' 68t, FPT 60t, APT 63t,  
FK, Collision BH to Shade dk, 8 BH to upper dk, Cur, Pilyds A. CP.

Fst in Shade dk.

Date of build. 1.2.22.



© 2019

Lloyd's Register  
Foundation

W15'8-0021

Second, Third & Fourth Deck, Single  
Bulk Angle, Plate, Toe Bulker Channel

12 x 4 x 4 .52 12 x 4 x 4 .52

Deck. Material and thickness  
Poop Deck Stringer Plate, breadth & thickness