

ions of Ship per Register, Length, 280.1 breadth, 45.2 depth, 18.1 Moulded Depth, 18 ft. 9 ins. Round of Beam

1

Sent to Chief Surveyors 7/7/09.

Received from Chief Surveyors

VESSEL'S NAME *Stl. L. S. Hopper Barge "Sand Grouse"* Report *Gls.*

No. 27918.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.5.02.)

Nature of Survey

1st Entry


When due

✦ A1 ("Steel") "Hopper Dredger"

1 DR (stl. pt. teak s.)

WB = Dtanks f 6', 87t.

FK. 5 BH. Lem. Lloyds A&CP Q29' F29'



W1581-0054

acing
idge or Pt. Awng. Deck, Angle,
bulb Angle Plate, or Tee Bulb....
gles on Inner Edg

48

48

„ Angles on ditto, No.....
Poop Deck Stringer Plate, breadth & thickness
Angle on ditto