

Working Pressure 180 lbs

Tested by hydraulic pressure to 360 lbs

Date of test 5/3/09

No. of 1

s/s Sand Grouse

lbs. 27918.

It is submitted the Glasgow Surveyors be requested to state whether a clerical error has not been made in giving the thickness of the main Boiler shell plates as 1 1/16" when the thickness shown on the approved plan is 1 3/32". & also to state the number of Donkey engines, as this has been omitted from their report.



© 2021

JGRJL

HSD.

7.7.09

5/2/17

Lloyd's Register Foundation

W1581-0059