

F.E.

Received by Chief Ship Surveyor 25.1.04

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME Soc. S. S. Sava

Report Gen No. 3019

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .		
Spar Sheerstrake . .		
Description of Framing:— <i>Ordinary as approved, being spaced (viz., ordinary, deep, zed, channel or bulb-angle). 1" clear than required.</i>		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed  $\dagger$  100 A 1 ("Steel") "For Towing and Salvage purposes" as recommended.

$\dagger$  100 A 1 ("Steel") "For Towing & Salvage purposes"

1 DR (Sec-WS)

W. B = APT 205

BK 6 $\frac{3}{4}$  4BH Gen. Lloyd's A & CP



C. N. J.  
© 2021  
25/1/04

Lloyd's Register Foundation

Book).  
Dock  
with F  
Beam  
of L  
es in S  
7x1  
20  
4  
30  
5-7/8  
25  
etc  
Inches  
Ship. in  
7.  
7.  
3/4  
7/4  
7/4  
7/4  
7/4  
7/4  
7.  
79/16