

1m.12.15.

Received by Chief Ship Surveyor

6.12.17

Received from Chief Ship Surveyor

F.E.

VESSEL'S NAME

Sz 7

Syringa

Rpt.

Bel

No. 7888

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

53

Depth "d"

16.75

Framing: Table No.

✓

Description

Built angle as approved.

Longitudinal No.

13623

Proportions

Length

Depth

14.28

Deck Sheerstrake + other scantlings as approved for vessels built for the A1 class.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed + A1 (Steel) for Government service as recommended.

2 10's (Steel u/s)

Cells 10B u/s 23C. DT. 7.20. FPT 11C. APT 23E.

FK. 12 BH. pt cem. Lloyd's A & P. 119'. 1381'. F35'



© 2021

Lloyd's Register Foundation

W1592-0091