

2

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME *SH. sc. "Corinaldo"* Report *Grk* No. *18467*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." — Extract from Sub-Committee's Report 24/5/32.)

1st No. *1*. SURVEY PARTLY HELD.When due *R-25* When proposed to be completed _____

Portion of Survey held, &c., _____

*Noted**To complete the survey see report.**Insert in RB*

3rd dk (stk) with 1.3.3 74 holds
in place of.
3rd dk (stk) in forward holds.

W160-0016

© 2012
Whitell
13. 11. 35-

Lloyd's Register
 Foundation