

COPY.

Lloyd's Register of Shipping.



Port MANILA, P. I.

November 7th, 1938.

This is to Certify *that I have*

Surveyed the ~~Boiler and Machinery of the~~ Starboard Main Engine No.5, 6, 7 & 8 Cylinders with all parts complete (numbered from forward) also thrust shaft and bearing of the American M/V "DON ESTEBAN" of ILOILO, P. I., 900 Tons Net, No.73372 in Register Book, - - - - -

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction, and that I have

Recommended *that the record of* SPECIAL SURVEY, - - - -

be made in the Register Book in the case of this vessel when the survey has been completed.

Parts now examined:—

Starboard Main Engine No.5, 6, 7 & 8 Cylinders, pistons, valves, heads, wrist pins, after crank shaft and journals, Starboard thrust shaft and bearing.

Fee as per account.

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly performed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society.

W161-0020