

# REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of London

No. in Reg. Book 406 Survey held at on the Wood, Iron or Steel S. R. Willet Date, First Survey Last Survey 19... Master

TONNAGE: GROSS 199, UNDER DEK 188, NET 63. Built at Gorb. By whom Gorb S.B. Reps. Ltd. When 1908-1. Owners Kelsall Bros & Baching Ltd. Port belonging to Hall. Owners' Address (G. Beeching & J. S. A. Kelsall)

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage. WB=CellDBorDBa feet; uE&B feet; f feet; total capacity tons. FPT tons; APT tons; MT feet tons.

Last Report, No. 20215 Port Hull. Particulars of Classification (which must be inserted precisely as in Register Book & Supplements). CHARACTER: \* for Special Survey. Date of last Survey and of Periodical Surveys. Years Assigned: 100. Machinery and Boiler Surveys (including date of N.B., if any): +L.M.C. 1-08.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS :-	Plates.	Frames.	E. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

  

PRESENT CONDITION OF THE	Stringers	Dblng. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Decks	Inner Bottom Plating	Engine Room Skylights	(State if on Felt.)
Caulking of Decks	State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month Year
Waterways	State if Tanks now tested	Scuppers	Boats
Coamings	Bulkheads	Cargo Hatchways	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Hatches	Condition, how ascertained
Outside Plating	Cement or Asphalt (State which.)	Planking of Wood Vessels	(State if wedges removed)
Caulking of ditto	Rudder	Caulking ditto	Sails
Rivets	Steering gear and its connections	Treenails ditto	Equipment letter
Breasthooks & Crutches	Windlass	Breasthooks & Stemson ditto	Anchors, No. of
Transoms	Have Pumps now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)
Frames	Have Sluice Valves now been examined and found efficient?	Timbers of Frames at openings ditto	length size
Reverse Frames	Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto	(on board)
Floors		Stringers, Clamps & Shelves ditto	Rule length size
Keelsons		Salting ditto	Hawser & Warps
		(State if examined.)	Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c. :- State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,10," or "to remain as classed and to have record of survey, 1,10, and the notations of ss No. 1-10 and ptND10, &c."

Survey Fee (per Section 28)	£		Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£		19
Travelling Expenses (if chargeable)	£		Received by me,
Second Surveyor's Fee (if any)	£		19

Committee's Minute Character Assigned. TUE. M. 19. 1912. Onil class as M. re-paint. Surveyor to Lloyd's Register of British & Foreign Shipping. Lloyd's Register Foundation. W1620-0086.