

12500, 12, 19

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Steel S.S. "ALGONQUIN" Report S.F. No. 3394

For the CHIEF SHIP SURVEYOR ~~CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required, and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.6.92.)

Nature of Survey _____

When due _____

100A.1. (steel) "Carrying Petroleum in bulk"

2 Dks. (steel) & Webframes. "Longitudinal Framing."

Cell DB. VEB 62' 197b. OT 50' 334b. FPT 104b. APT 70b.

FK. 14BH (9 to upper Dk. 5 to 2nd Dk.) plasp. AYCP.

P 106', B 50', F 42'.

M dry. aft.

M *RES*
10-12-20
Lloyd's Register
Foundation

W1624-0172