

For the information of Surveyors and the Committee only.

Received at _____ Office, _____ 11

(Report on Machinery, No. 89569 Port Moz)

No. V 1569

ENGINE or BOILER VALVES or CONNECTIONS.

by Messrs John A Grant & Co of Cardonald
for the Engines or Boilers No³³³⁴ 301/32 being constructed by Messrs
N.E. Mac. E. & Lth. of Runcorn / Tyne

have been inspected by me as set forth below, and found to be, so far as can be seen, sound and free from defects.

These have been despatched to Above

Stamp Mark.

LLOYD'S TEST.

360 + 370 lbs.

No. 1326, 1327, 1328.

M. Lane

Aug. no. 27. 10. 1932

Number and	Description.
1	...
2	...
3	...
4	...
5	...
6	...
7	...
8	...
9	...
10	...
11	...
12	...
13	...
14	...
15	...
16	...
17	...
18	...
19	...
20	...
21	...
22	...
23	...
24	...
25	...
26	...
27	...
28	...
29	...
30	...
31	...
32	...
33	...
34	...
35	...
36	...
37	...
38	...
39	...
40	...
41	...
42	...
43	...
44	...
45	...
46	...
47	...
48	...
49	...
50	...
51	...
52	...
53	...
54	...
55	...
56	...
57	...
58	...
59	...
60	...
61	...
62	...
63	...
64	...
65	...

$\frac{1326}{2334},$ - One Single 2" Spring Safety Valve. } 14
 $\frac{1327}{2301/32},$ - One Single 2" Ditts }
 $\frac{1328}{2306/32},$ - Three Single 2" Ditts }

Hydraulic Test :

lbs. per square inch. 1326 x 1327, - 360. 1328, - 370

Other Tests, if any.

Dates when Inspected.

26. 10. 1932.

31.11.28.

1.30

Lloyd's Register
Foundation *Three.*

W163-0010