

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Steel Screw Trawler "INDIAN STAR"

Rpt.

Mab

No. 15773

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long. No. 2405

Depth "d" -

2nd Long. No. 6772

Proportions =  $\frac{L}{D}$  -

Framing Angle frames as approved

Sheerstrake As approved (increased)

Additional stiffening has been fitted to the framing  
in the Bunkers and Fish Room.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

\*100A1 "Steam Trawler"

1 Dk.

Side Tanks in E.R. 12t, DT f 22t, APT 6t

BK 7 $\frac{1}{2}$ ", 4 BH, Cem. Lloyd's A & CP

Q 84', F 29'

© 2021

Lloyd's Register  
Foundation

W1634-0188

33

20



© 2021  
Lloyd's Register  
Foundation