

1

Sent to Chief Surveyors

16/11/10

Received from Chief Surveyors

VESSEL'S NAME

St. S. Coronada

Report

Geo

No.

29493

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.5.92.)

Nature of Survey

Struct. survey

When due

WRECK
SECTION
No.

+ 100 A.1 (2nd) Shade deck
2 Dr (N - 1st - W6) + Shade deck (2nd. Deck S)
W13 - Cull D73a 120' u 3' x 35' f 15' 602t D7a 55' 795t F.P.T 644
F.K. 53H to u Dr & 1 to 2nd Dr Gen. Lloyd at G.P. For Shade deck 56'

Mr

DBA
16/11/10



© 2021

Lloyd's Register
Foundation