

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Steel S. S. "DIXIE ARROW" Report Phl No. 4285**For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/02.)

Nature of Survey _____

When due _____

* 100 A-1. (Steel) Shelter Deck with foreboard Carrying petroleum in bulk
 2 Dks (Steel) + Shelter Dk (Steel) + Webframes, longitudinal framing
 Cell Dk a 19' U/E + B 7'6" 436 t, IT f 40' bulk, Tween Dk tank aft 100t.

FPT 2296, APT 1316


FK, 16 BH (Collision BH to Shelter Dk, 9 BH to Upper Dk, 6 BH to 2nd Dk)

ft Cen, Av CP, Mchys aft

So. 30/1/22

See letter
20.2.22

It is concluded the lawsers + works are as required but the Surveyors
 should be requested to state if this is so



© 2021

Lloyd's Register
Foundation

W164-0231