

4m.8.12.

Received by Chief Ship Surveyor 15. 10. 13

Received from Chief Ship Surveyor

VESSEL'S NAME M. S. Guelder Rose Rpt. Rot. No. 8809

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

First Entry

It is submitted the Hull Surveyors be informed that this vessel has proceeded to their port for her Engines and Boilers to be fitted, and that to complete the survey on the hull the engine and boiler casings require to be riveted up.


They should be requested to give the case the necessary attention, and on completion of the work to furnish a report on Form 8 for the information of the Committee.

Lr. 15. 10. 13

*M. W. W.*

15. 10. 13

© 2020



Lloyd's Register  
Foundation

Angles to O  
Floo  
Brackets at intermd. fring., wdt.

br'dth & thickness

thruays

om built N.V. Scheeps  
"de Merwede"  
Shipping Inves

Book.)  
rdon  
don  
ry Doc  
of Decks  
of Tiers  
Round of  
Dk. Beam  
ches  
ze in  
Ship.  
Spac  
SI  
Zinder  
and  
14. 4 1/2  
hes  
hip. Inches  
in Ship.  
9 .36  
1/2 3 1/2  
2 .36  
1/2 3  
6 3  
1 3  
42  
36  
3 1/2 x 3 1/2