

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report... When handed in at Local Office... 22/10/37 Port of **EWCASTLE-ON-TYNE**

No. in Reg. Book... Survey held at **JARROW-ON-TYNE**. Date, First Survey... and Last Survey **20 Oct 1937**

21135 on the ~~Wood, Iron or Steel~~ **"BECKENHAM"** Built at **DUNDEE** By whom **CALEDON S. BYE & CO LTD** When **1934**

TONNAGE - GROSS **4634** Owners **BRITAIN S.S. CO LTD** Owners' Address... NET **2402** Managers **WATTS, WATTS & CO LTD** Port belonging to **LONDON**

Surveyed Afloat or in Dry Dock? **Dry Dock** Name of Dock **MERCANTILE DRY DOCK** Destined Voyage... Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

WB=CellDBorDBa... feet; uE&B... feet; f... feet } total capacity... tons. FPT... tons; APT... tons; MT... feet tons. }
N.B.—All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. ... Port ...
In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

REPAIRS, OR EXAMINATION AS PER RULE, FOR **EXAMINATION OF BOTTOM AND PAINTING prior to proceeding on first voyage.**

Now Done:- Vessel placed in Dry Dock. Bottom and Rudder cleaned examined, found in good condition and recoated.

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE		State if Tanks have been examined inside		Air and Sounding Pipes		Copper, or Y.M. of Wood Vessels	
Deck	State if Tanks now tested	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels	Boats	State if on Feet.	When put on, Month	Year
Caulking of Decks	Bulkheads	Dbng. Plates under Sounding Pipes	Boats	Masts, Yards, &c.	Condition, how ascertained	(State if wedges removed)	
Coamings	Ceiling	Engine Room Skylights	Sails	Equipment letter			
Beams & Fastenings	Cement or Asphalt (State which.)	Coal Bunkers, Open'gs, Lids, &c.	Equipment letter	Equipment letter			
Outside Plating	Rudder	Oil Bunkers	Equipment letter	Equipment letter			
" " in way of sidelights	Steering gear and its connections	Scuppers	Equipment letter	Equipment letter			
Breasthooks	Windlass	Cargo Hatchways	Equipment letter	Equipment letter			
Transoms	Have pumps now been examined and found efficient?	Hatches	Equipment letter	Equipment letter			
Frames	Have Sluice Valves now been examined and found efficient?	Planting of Wood Vessels	Equipment letter	Equipment letter			
Reverse Frames	Have Watertight Doors now been examined and found efficient?	Caulking	Equipment letter	Equipment letter			
Longitudinals	Have Ventilators and their Coamings been examined and found efficient?	Treadmills	Equipment letter	Equipment letter			
Transverses		Breasthooks & Stems	Equipment letter	Equipment letter			
Floors		Transoms Pointers, & Crutches	Equipment letter	Equipment letter			
Keelsons		Timbers of Frame at openings	Equipment letter	Equipment letter			
Stringers		Ditto Ditto at other places	Equipment letter	Equipment letter			
Inner Bottom Plating		Stringers, Clamps & Shelves	Equipment letter	Equipment letter			
		Salting (State if examined.)	Equipment letter	Equipment letter			

General Observations, Opinion as to Class, Recommendation, &c. :-
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and pND24, &c."

This Report is forwarded for the information of the Committee.

Survey Fee (per Section 29)	£	Fees applied for,	19
Special Damage or Repair Fee (if any) (per Sec. 29)	£	Received by me,	19
Travelling Expenses (if chargeable)	£		
Second Surveyor's Fee (if any)	£		

Committee's Minute... TUE 2 NOV 1937
Character Assigned **See Item 9007**

