

COPY.

Lloyd's Register of Shipping.



Port

NEWCASTLE, N.S.W.,

10th. February, 1942

This is to Certify that

E. M. Hughes,

the undersigned Surveyor to this Society did at the request of

THE MASTER

survey the M. V. "HAV" of Oslo, 5062 Gross Registered Tons, for the purpose of ascertaining the nature and extent of the damage stated to have been sustained to the vessel by Grounding off Steel Works wharf in this harbour while swinging to berth there at about 2.15 p.m. and again at 2.35 p.m. on the 5th. inst.. FOR FURTHER PARTICULARS see Log Books.

UPON EXAMINATION, vessel in Walsh Island dry dock on the 9th. inst., the undersigned

FOUND

On the Port side

In P. strake, 7th. plate from fwd. scored slightly for a length of about 25' and Bilge Keel in way for about 7'. Bilge keel also in a slightly wavy condition at about middle length.

E. M. Hughes

SURVEYOR TO LLOYD'S REGISTER

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."